

4/23/2018 ACR # 1 0334L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	OPEN WET		5 5 5	0330
<i>Remarks</i>				
12R/30L	OPEN WET		5 5 5	0330
<i>Remarks</i>				
11/29	OPEN WET		5 5 5	0330
<i>Remarks</i>				
6/24	OPEN WET		5 5 5	0330
<i>Remarks</i>				

GENERAL TAXIWAY CONDITIONS

TWY H LEAD-OFF CNTRLN ON RWY 30R NOT STD.
TWY E2 SPHPS REMOVED FOR RWY 12L/30R.
TWY D BETWEEN TWY K AND TWY L IRREGULAR SURFACE.
TWY E1 ENHANCED CL MARKINGS NOT STD

Status	Braking Action	Status	Braking Action
A	OPEN	F6	OPEN
A1	OPEN	F7	OPEN
A2	OPEN	H	OPEN
A3	OPEN	J	OPEN
A4	OPEN	K	CLSD BTN RWY 12L AND RWY 12R
A5	OPEN	K1	OPEN
A6	OPEN	L	OPEN
B	OPEN	M	OPEN
C	OPEN	N	OPEN
D	OPEN	P	OPEN
D1	OPEN	Q	OPEN
D3	OPEN	R	OPEN
D4	OPEN	S	CLSD RWY 12R/30L & TWY E
D5	OPEN	S1	OPEN
E	CLSD BTN TWY L AND TWY E1	T	OPEN
E1	OPEN	U	OPEN
E2	OPEN	V	OPEN
F	OPEN	V1	OPEN
F4	OPEN	V2	OPEN

GENERAL RAMP CONDITIONS

TXL C NORTH EDGE WEST TWY N IRREGULAR SFC.
APRON GATE B4, C8, D2, C7, C19, C35 WIP OPEN EXCAVATION LGTD AND BARRICADED. APRON GATE E2, E33 WIP LGTD AND BARRICADED.
CHARLIE PAD SPOTS 2, 3, 4 AND 5 CLSD.
APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS