

5/22/2018 ACR # 4 1227L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	OPEN			
Remarks				
12R/30L	OPEN			
Remarks				
11/29	OPEN			
Remarks				
6/24	CLOSED			
Remarks				

GENERAL TAXIWAY CONDITIONS

TWY H LEAD-OFF CNTRLN ON RWY 30R NOT STD.  
TWY E2 SPHPS REMOVED FOR RWY 12L/30R.  
TWY E1 ENHANCED CL MARKINGS NOT STD.

Status	Braking Action	Status	Braking Action
A	CLSD BTN APCH 6 & TWY T	F6	OPEN
A1	OPEN	F7	OPEN
A2	OPEN	H	OPEN
A3	OPEN	J	OPEN
A4	OPEN	K	CLSD BTN RWY 12L/30R & RWY 12R/30L
A5	OPEN	K1	OPEN
A6	OPEN	L	OPEN
B	OPEN	M	OPEN
C	OPEN	N	OPEN
D	OPEN	P	OPEN
D1	OPEN	Q	OPEN
D3	OPEN	R	OPEN
D4	OPEN	S	CLSD BTN RWY 12R/30L & TWY E, APCH 6 & T
D5	OPEN	S1	OPEN
E	CLSD BTN TWY L AND TWY E1	T	OPEN
E1	OPEN	U	OPEN
E2	OPEN	V	CLSD BTN TWY V2 & 12R/30L
F	OPEN	V1	OPEN
F4	OPEN	V2	OPEN

GENERAL RAMP CONDITIONS

TXL C NORTH EDGE WEST TWY N IRREGULAR SFC.  
APRON GATE E2, E14, A8, C27, C35, & T1 RAMP EAST OF GATE A2 WIP OPEN EXCAVATION LGTD AND BARRICADED.  
CHARLIE PAD SPOTS 2, 3, 4 AND 5 CLSD.  
APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED.

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS