

12/10/2018 ACR # 3 0505L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	OPEN			
Remarks				
12R/30L	OPEN			
Remarks				
11/29	OPEN			
Remarks				
6/24	OPEN			
Remarks				

GENERAL TAXIWAY CONDITIONS

TWY K1 CLSD TO ACFT WINGSPAN MORE THAN 118FT.
 TWY J HLDG PSN SIGN SOUTH & NORTH SIDE FOR RWY 12R/30L NOT STD.
 TWY S HLDG PSN SIGN EAST SIDE BTN RWY 12R/30L AND TWY E NOT STD.
 TWY E2 SPHPS REMOVED FOR RWY 12L/30R.
 TWY J CHANGED TO TWY H EFFECTIVE NOV 8. TWY H CHANGED TO TWY G EFFECTIVE NOV 8.
 TWY K BTN TXL C AND TWY E CHANGED TO TWY J EFFECTIVE NOV 8.

Status	Braking Action	Status	Braking Action
A	OPEN	F6	OPEN
A1	OPEN	F7	OPEN
A2	OPEN	G	OPEN
A3	OPEN	H	OPEN
A4	OPEN	J	OPEN
A5	OPEN	K	OPEN
A6	OPEN	K1	CLSD UNTIL 12/21/18
B	OPEN	L	OPEN
C	OPEN	M	OPEN
D	OPEN	N	OPEN
D1	OPEN	P	OPEN
D3	OPEN	Q	OPEN
D4	OPEN	R	OPEN
D5	OPEN	S	OPEN
E	OPEN	S1	OPEN
E1	OPEN	T	OPEN
E2	OPEN	U	OPEN
F	OPEN	V	OPEN
F4	OPEN	V1	OPEN
		V2	OPEN

GENERAL RAMP CONDITIONS

CHARLIE PAD SPOTS 3, 4, AND 5 CLSD.
 APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED.
 CHARLIE PAD CLSD TO ACFT WINGSPAN MORE THAN 78FT.
 LIMA PAD CLSD TO XNG WIP DEICING

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS

RWY 12L/30R SAFETY AREA NOT STD EAST EDGE RWY 30R BLAST PAD.