

6/21/2018 ACR # 2 0410L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	OPEN			
Remarks	12L TDZ Lights Non-Standard			
12R/30L	OPEN			
Remarks				
11/29	OPEN			
Remarks				
6/24	OPEN			
Remarks				

GENERAL TAXIWAY CONDITIONS

TWY H LEAD-OFF CNTRLN ON RWY 30R NOT STD.
 TWY E2 SPHPS REMOVED FOR RWY 12L/30R.
 TWY E1 ENHANCED CL MARKINGS NOT STD.
 TWY E2 BTN RWY 12L/30R AND TWY E WEST EDGE IRREGULAR SFC

Status	Braking Action	Status	Braking Action
A	OPEN	F6	OPEN
A1	OPEN	F7	OPEN
A2	OPEN	H	OPEN
A3	OPEN	J	OPEN
A4	OPEN	K	CLSD BTN RWY 12L/30R & TWY D
A5	OPEN	K1	OPEN
A6	OPEN	L	OPEN
B	OPEN	M	OPEN
C	OPEN	N	OPEN
D	CLSD BTN TWY D3 & TWY J	P	OPEN
D1	OPEN	Q	OPEN
D3	OPEN	R	OPEN
D4	OPEN	S	CLSD BTN RWY 12R/30L & TWY E
D5	OPEN	S1	OPEN
E	CLSD BTN TWY L AND TWY E1	T	OPEN
E1	OPEN	U	OPEN
E2	OPEN	V	OPEN
F	OPEN	V1	OPEN
F4	OPEN	V2	OPEN

GENERAL RAMP CONDITIONS

TXL C NORTH EDGE WEST TWY N IRREGULAR SFC.
 APRON GATE C16, C32 & T1 RAMP EAST OF GATE A2 WIP OPEN EXCAVATION LGTD AND BARRICADED.
 APRON GATE C27, C35, E2 WIP LGTD AND BARRICADED.
 CHARLIE PAD SPOTS 2, 3, 4 AND 5 CLSD.
 APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED.
 CHARLIE PAD CLSD TO ACFT WINGSPAN MORE THAN 78FT.

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS