

7/20/2018 ACR # 8 1457L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	OPEN			
Remarks	12L TDZ Lights Non-Standard			
12R/30L	OPEN			
Remarks				
11/29	OPEN			
Remarks				
6/24	OPEN			
Remarks				

GENERAL TAXIWAY CONDITIONS

TWY H LEAD-OFF CNTRLN ON RWY 30R NOT STD.
 TWY H HLDG PSN MARKINGS FOR RWY 12L/30R NOT STD
 TWY E2 SPHPS REMOVED FOR RWY 12L/30R.
 TWY E1 ENHANCED CL MARKINGS NOT STD.
 TWY E2 BTN RWY 12L/30R AND TWY E WEST EDGE IRREGULAR SFC
 TWY A5 EDGE LGHT BTN TWY A AND TWY B NOT STD.

Status	Braking Action	Status	Braking Action
A OPEN		F6 OPEN	
A1 OPEN		F7 OPEN	
A2 OPEN		H OPEN	
A3 OPEN		J OPEN	
A4 OPEN		K CLSD	BTN RWY 12L/30R & TWY D
A5 CLSD	BTN TWY A & TWY B	K1 OPEN	
A6 OPEN		L OPEN	
B OPEN		M OPEN	
C OPEN		N OPEN	
D CLSD	BTN TWY D3 & TWY J	P OPEN	
D1 CLSD		Q OPEN	
D3 OPEN		R OPEN	
D4 OPEN		S CLSD	BTN 12R/30L & TWY E
D5 OPEN		S1 OPEN	
E CLSD	BTN TWY L AND TWY E1	T OPEN	
E1 OPEN		U OPEN	
E2 OPEN		V OPEN	
F OPEN		V1 OPEN	
F4 OPEN		V2 OPEN	

GENERAL RAMP CONDITIONS

TXL C NORTH EDGE WEST TWY N IRREGULAR SFC.
 APRON GATE T1 RAMP EAST OF GATE A2, GATE C15, GATE C18 WIP OPEN EXCAVATION LGTD AND BARRICADED, WIP GATE A3 LGTD AND BARRICADED
 CHARLIE PAD SPOTS 3, 4, AND 5 CLSD.
 APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED.
 CHARLIE PAD CLSD TO ACFT WINGSPAN MORE THAN 78FT.

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS