

8/18/2018 ACR # 7 1111L

RUNWAYS

Status	Conditions	Depth	RwyCC	Time
12L/30R	CLOSED TIL 8/29 Remarks 12L TDZ Lights Non-Standard			
12R/30L	OPEN Remarks			
11/29	OPEN Remarks			
6/24	OPEN Remarks			

GENERAL TAXIWAY CONDITIONS

TWY H LEAD-OFF CNTRLN ON RWY 30R NOT STD TWY K1 CLSD TO ACFT WINGSPAN MORE THAN 79FT  
 TWY K HLDG PSN SIGN SOUTH & NORTH SIDE FOR RWY 12R/30L NOT STD  
 TWY E2 SPHPS REMOVED FOR RWY 12L/30R. TWY S HLDG PSN SIGN NORTH SIDE FOR RWY 12R/30L NOT STD  
 TWY E1 ENHANCED CL MARKINGS NOT STD. TWY K BTN HAITH CARGO RAMP ACCESS AND TWY K1 EAST EDGE  
 IRREGULAR SFC  
 TWY B BTN TWY A3 AND TWY A4 NORTH EDGE IRREGULAR SFC

Status	Braking Action	Status	Braking Action
A	OPEN	F6	OPEN
A1	OPEN	F7	OPEN
A2	OPEN	H	CLSD BTN RWY 12L/30R AND TWY E
A3	OPEN	J	CLSD BTN TWY F & TWY E
A4	OPEN	K	OPEN
A5	OPEN	K1	OPEN
A6	OPEN	L	CLSD BTN TWY F & TWY E
B	OPEN	M	OPEN
C	CLSD BTN RWY 24 & TWY U	N	OPEN
D	OPEN	P	CLSD BTN TWY F & TWY E
D1	OPEN	Q	OPEN
D3	OPEN	R	OPEN
D4	OPEN	S	OPEN
D5	OPEN	S1	OPEN
E	CLSD BTN APCH 30R & TWY H	T	CLSD BTN RWY 24 AND TWY D
E1	CLSD	U	OPEN
E2	CLSD	V	OPEN
F	CLSD BTN TWY F4 & TWY J	V1	OPEN
F4	OPEN	V2	OPEN

GENERAL RAMP CONDITIONS

TXL C NORTH EDGE WEST TWY N IRREGULAR SFC.  
 CHARLIE PAD SPOTS 3, 4, AND 5 CLSD.  
 APRON CHARLIE PAD WIP OPEN EXCAVATION 60FT LONG, 102FT WIDE, 25FT DEEP LGTD AND BARRICADED.  
 CHARLIE PAD CLSD TO ACFT WINGSPAN MORE THAN 78FT.  
 APRON TERMINAL ONE AIRLINE RAMP WIP GATE E40 LGTD AND BARRICADED.

Conditions	Braking Action	Snow Piles
Terminal One		
Terminal Two		

MISCELLANEOUS